

2011 - 2012



Ermax[®]
www.ermax.fr

The logo features the word "Ermax" in a bold, stylized, rounded font with a white-to-black gradient and a thick black outline. Below it, the website address "www.ermax.fr" is written in a smaller, cursive-style font. The entire logo is set against a background of glowing white decorative flourishes and a radial light effect.

Guide d'utilisation
User guide

SOMMAIRE / CONTENTS

Français	03 à 07
-----------------------	---------

AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN ABS..... 03 à 05

- Généralités..... 03
- Passage de roue / Support de plaque / Garde-boue..... 04
- Sabot moteur / Flanc de carénage / Écobe de radiateur..... 05

AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN PLEXIGLAS®..... 06 à 07

- Généralités..... 06
- Bulle Aéromax®..... 07

English	08 to 11
----------------------	----------

WARNINGS ABOUT USE AND FITTING OF ABS PARTS08 to 10

- Generalities..... 08
- Undertray / Plate holder / Rear hugger..... 09
- Belly pan / Low fairing / Scoop by air..... 09 to 10

WARNINGS ABOUT USE AND FITTING OF PLEXIGLAS® PARTS 10 to 11

- Generalities..... 10 to 11
- Aéromax® screen..... 11

ANNEXE / ENCLOSURE.....	12 à 19
--------------------------------	----------------

AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN ABS

GENERALITES

- Tout accessoire monté ne sera plus considéré comme neuf et ne sera **ni repris ni échangé**.
- Les pièces peintes et vernies ne sont pas garanties contre les lavages vapeur « haute pression » ou les produits nettoyants agressifs (dissolvant, essence, détergent ...) qui peuvent les endommager et décoller le vernis. Nous conseillons d'ailleurs, d'après les données techniques de nos fournisseurs en peinture, d'**attendre un mois** afin d'obtenir une polymérisation complète du vernis. Essayez immédiatement les liquides de frein ou de batterie qui pourraient déborder sur les accessoires.
- Toute casse ou fente due à des écoulements de produits corrosifs n'est pas garantie (liquide de frein, acide de batterie, essence ...).
- Les accessoires Ermax sont conçus pour des **montes d'origine**. Ils ne sont pas garantis s'ils sont utilisés dans d'autres conditions.
- En raison des tolérances de fabrication des véhicules, indépendantes de notre volonté, certains produits Ermax peuvent nécessiter des ajustements lors de leur fixation.
- Le montage des pièces n'est pas garanti (serrage excessif, non respect des notices de montage ...). Les pièces détériorées suite à un mauvais montage ne seront ni reprises, ni échangées.
- Les produits fabriqués par Ermax sont garantis pendant **une durée d'un an** contre tout vice de fabrication. Ermax n'est pas responsable en cas de détérioration d'une pièce de la moto suite au montage de l'un de ses accessoires.
- Attention aux serrages excessifs qui pourraient abîmer ou casser nos accessoires en plastique et les vis en aluminium.
- Certains produits sont fabriqués sur commande spéciale et ne sont ni repris, ni échangés, ou sont repris avec décotes.
- Toute réclamation concernant un produit doit être effectuée dans les 72 heures suivant sa livraison, via le revendeur Ermax. Ne pourront être repris ou échangés les articles ayant subi une détérioration ou retournés hors délai.
- Les produits Ermax sont livrés avec une notice montage. Ceux qui n'ont pas de notice se montent à la place de l'équipement d'origine, avec la visserie d'origine.

AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN ABS

PASSAGE DE ROUE / SUPPORT DE PLAQUE / GARDE-BOUE

- Toute détérioration des passages ou supports due à la présence d'une charge de poids excessive ne sera pas garantie (chaîne anti-ivol, cadenas, U ...).
- Certains pneus, conformes aux standards ETRTO, peuvent être en réalité plus hauts et plus larges que les dimensions gravées sur le pneu (jusqu'à + 10 mm). Ils peuvent être **incompatibles avec les passages de roue et garde-boue que nous avons conçus avec les pneus montés d'origine et dont les dimensions correspondent à celles gravées sur le pneu.**
- Il est conseillé de vérifier l'inclinaison de la plaque minéralogique avant le montage, et si nécessaire, de plier le support plaque métallique de manière à conserver une inclinaison dans les normes (**ne pas plier le support métallique quand il est inséré dans la pièce en ABS**) (pièce fournie avec certains passages de roue et supports de plaques).
- Il est nécessaire de durcir l'amortisseur arrière lors de conduite chargée ou sur routes bosselées.
- L'écartement des clignotants intégrés dans nos feux à leds ainsi que sur certains passages de roue et supports de plaque n'est pas homologué en France. Nous vous conseillons de poser des clignotants additionnels espacés d'au moins 18 cm.



- Nous vous rappelons que la loi française impose la présence d'un catadioptre à l'arrière de tous les véhicules deux roues.

AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN ABS

SABOT MOTEUR / FLANC DE CARENAGE ECOPE DE RADIATEUR

- Déplacer les durites qui pourraient couler à l'intérieur des sabots ou flancs (en particulier les durites de trop plein d'huile et d'essence des 600 Hornet 2003/2006). Toute casse due à des **écoulements de produits corrosifs** n'est pas garantie.
- Les sabots et flancs de carénage ne seront ni repris ni échangés en cas de frottement lors d'une conduite "sportive", ou lors du franchissement de trottoirs, dos d'âne ... Le montage des accessoires Ermax est prévu pour une **utilisation routière normale**.
- Une fois montées, les pièces ne doivent avoir aucun contact avec le moteur et doivent être suffisamment éloignées de la ligne d'échappement. Il peut être nécessaire de modifier légèrement les angles des pattes de fixations pour ajuster les accessoires à chaque moto (**ne pas plier les pattes de fixation quand elles sont montées sur les pièces**).
- Les vis fixées au niveau des radiateurs doivent être isolées avec des rondelles plastiques (fournies si nécessaire).
- Les grilles alu se placent, accessoirement, au niveau des entrées d'air.



AVERTISSEMENTS CONCERNANT L'UTILISATION ET LE MONTAGE DES PIÈCES EN PLEXIGLAS®

GENERALITES

- Tout accessoire monté ne sera plus considéré comme neuf et ne sera **ni repris ni échangé**.
- Les bulles abîmées par un **lavage inadéquat** ne sont pas garanties (dissolvant, essence, détergent, produits abrasifs, corrosifs...). Essuyez immédiatement les liquides de frein ou de batterie qui pourraient déborder sur les accessoires.
- Les accessoires Ermamax sont conçus pour des **montes d'origine**. Ils ne sont pas garantis s'ils sont utilisés dans d'autres conditions.
- En raison des tolérances de fabrication des véhicules, indépendantes de notre volonté, certains produits Ermamax peuvent nécessiter des ajustements lors de leur fixation.
- Le montage des pièces n'est pas garanti (serrage excessif, non respect des notices de montage ...). Les pièces détériorées suite à un mauvais montage ne seront ni reprises, ni échangées.
- Les produits fabriqués par Ermamax sont garantis pendant **une durée d'un an** contre tout vice de fabrication. Ermamax n'est pas responsable en cas de détérioration d'une pièce de la moto suite au montage de l'un de ses accessoires.
- Certains produits sont fabriqués sur commande spéciale et ne sont ni repris, ni échangés, ou sont repris avec décotes.
- Toute réclamation concernant un produit doit être effectuée dans les 72 heures suivant sa livraison, via le revendeur Ermamax. Ne pourront être repris ou échangés les articles ayant subi une détérioration ou retournés hors délai.
- Les produits Ermamax sont livrés avec une notice montage. Ceux qui n'ont pas de notice se montent à la place de l'équipement d'origine, avec la visserie d'origine.

**AVERTISSEMENTS CONCERNANT L'UTILISATION
ET LE MONTAGE DES PIÈCES EN PLEXIGLAS®**

BULLE AEROMAX®

- Depuis 1998, les plastiques des nouveaux ensembles compteurs fondent et se déforment à 70°C au lieu de 200°C ! Il est impératif de protéger vos compteurs quand la moto est stationnée au soleil ou devant un mur blanc. Aucune garantie / échange / remboursement ne sera pris en compte dans le cas d'un sinistre.
- Ermax fournit avec ses bulles Aéromax une protection de compteurs, à placer entre la bulle et les compteurs lorsque la moto est stationnée au soleil.



WARNINGS ABOUT USE AND FITTING OF ABS PARTS

GENERALITIES

- Accessories gone up on the motorbike will not be any more considered as new and will be **neither retaken nor exchanged**.
- Painted and varnished parts are not guaranteed against high pressure steam washes or aggressive cleaning products (solvent, thinner, benzine ...) which can damage them and unstuck the varnish. We advise moreover, according to the technical data of our painting suppliers, **to wait one month** to obtain a complete polymerization of varnish. Wash immediately brake or battery fluid which may flow on accessories.
- Any deterioration due to flows of corrosive products is not guaranteed (liquid of brake or battery, essence ...).
- Ermax accessories are foreseen for **original equipments**. They will not be guaranteed if they are used in others conditions.
- Due to vehicles made tolerances, beyond our control, some Ermax products might need adjustings to fit.
- Parts assembly is not guaranteed (extreme clamping, fitting instructions not respected ...). Parts damaged following a wrong assembly will be neither retaken, nor exchanged.
- Products manufactured by Ermax are guaranteed for a **period of one year** against any manufacturing defect. Ermax is not liable for damage to a part of the motorbike following the mounting of one of its accessories.
- Care to excessive clampings which may damage or break our plastic accessories and aluminium screws.
- A few products are made on special order and are neither retaken, nor exchanged, or are retaken with drops.
- Any claim about a product must be made within 72 hours following its delivery, via the Ermax dealer. Products that have suffered deterioration or returned after the deadline will not be neither retaken nor exchanged.
- Ermax accessories are delivered with fitting instructions. Those who have not instructions are fitted in place of original equipment, with original screws.

WARNINGS ABOUT USE AND FITTING OF ABS PARTS

UNDERTRAY / PLATE HOLDER / REAR HUGGER

- Any deterioration of the undertrays or plate holders due to the presence of any excessive load will not be guaranteed.
- A few tyres, faithful to ETRTO standards, may be in fact bigger and higher than dimensions engraved on the tyre (until + 10 mm). They may be **not compatible with undertrays and rear huggers which we made with original tyres and whose dimensions correspond to these ones engraved on tyre.**
- It is advised to check the slope of the number plate before assembly, and if necessary, fold the plate metal support so as to preserve a slope in the standards (**do not fold the metal support while inserted in the ABS part**) (part provided with a few undertrays and plate holders).
- It is necessary to harden the rear shock absorber while driving with load or on dented roads.



BELLY PAN / LOW FAIRING / SCOOP BY AIR

- Move hoses so that they do not fall inside the belly pans or low fairings (especially gasoline and oil flowing hoses of 600 Hornet 2003/2006). Any deterioration due to **flows of corrosive products** is not guaranteed.
- Belly pans and low fairings will be neither retaken nor exchanged in case of rubbing during a "sports" driving, or during the clearing of pavements, uneven road surfaces ... The fitting of Ermax accessories is planned for a **normal road use.**

WARNINGS ABOUT USE AND FITTING OF ABS PARTS

- Once fitted, belly pans or loaw fairings must have no contact with motor and has to be far enough from complete exhaust system. Fitting brackets' angles may be a little modified in order to adjust the accessory to every motorbike (**do not fold the fixing brackets while fitted on parts**).
- Screws fitted at radiators level have to be isolated with plastic washers (provided if necessary).
- Aluminium railings can be put in option at the air intakes.



WARNINGS ABOUT USE AND FITTING OF PLEXIGLAS® PARTS

GENERALITIES

- Accessories gone up on the motorbike will not be any more considered as new and will be **neither retaken nor exchanged**.
- Screens damaged by an **inadequat washing** are not guaranteed (abrasive, corrosive ... products, solvent, thinner, benzine ...). Wash immediately brake or battery fluid which may flow on accessories.
- Ermax accessories are foreseen for **original equipments**. They will not be guaranteed if they are used in others conditions.
- Due to vehicles made tolerances, beyond our control, some Ermax products might need adjustings to fit.

WARNINGS ABOUT USE AND FITTING OF PLEXIGLAS® PARTS

- Parts assembly is not guaranteed (extreme clamping, fitting instructions not respected ...). Parts damaged following a wrong assembly will be neither retaken, nor exchanged.
- Products manufactured by Ermax are guaranteed for a **period of one year** against any manufacturing defect. Ermax is not liable for damage to a part of the motorbike following the mounting of one of its accessories.
- A few products are made on special order and are neither retaken, nor exchanged, or are retaken with drops.
- Any claim about a product must be made within 72 hours following its delivery, via the Ermax dealer. Products that have suffered deterioration or returned after the deadline will not be neither retaken nor exchanged.
- Ermax accessories are delivered with fitting instructions. Those who have not instructions are fitted in place of original equipment, with original screws.

AEROMAX® SCREEN

- Since 1998, the plastics of new speedometers melt and get out of shape at 70°C instead of 200 °C ! It's imperative to protect your speedometers when your motorbike is parked at sun or in front of a white wall. No guarantee / exchange / refund will be awarded in the event of a disaster.
- Ermax provide one dashboard protection, to place between the screen and the dashboard when motorbike is parked at sun.



Teilgutachten Nr.: 18 10 07 8302 (4. Neufassung)
 Hersteller: Fechter-Drive
 Typ: Tail Skirt TS

Fortsetzung zu 1. Verwendungsbereich:

Fahrzeug-hersteller	Typ	Handels-bezeichnung	ABE-Nr. / EG-BE-Nr.	Ausführung
Suzuki	AD	GSX-R 600 -00	H 583	10
	BG	GSX-R 600 01-	e4*0100	11
	WVB2	GSX-R 600	e4*0253	52
	WVB5	GSF 650 Bandit	e4*0359	
	GV75A	GSF 1200 / S	H 344	12
	WVA9	GSF 1200 / S	e4*0086	13
	A1	GSX 1300	e4*0012	35
	WVBN	GSX 1400	e4*0116	33
	AV	SV 650	K 329	14
	WVBY	SV 650, S	e4*0192	45
	AG	TL 1000 S	H 632	15
	GR7DB	GSX-R 750	H 254	16
	WVBD	GSX-R 750	e4*0058	23
	WVB3	GSX-R 750	e4*0261	52
	WVBL	GSX-R 1000	e4*0108	23
	WVBZ	GSX-R 1000	e4*0183	47
WVB6	GSX-R 1000	e4*0375	53	
WVBX	SV 1000, S	e4*0191	46	
Triumph	T509	Speed Triple	H 682	17
	S95N	Speed Triple	e11*00040*	41
Yamaha	RJ02	FZS 600	H 988	18
	RJ02	FZS 600 Fazer	H 988	34
	RJ03	YZF R6 -00	K 265	19
	RJ05	YZF R6	e13*0060*	48
	RN06	FZS 1000	e1*00103*	20
	RN01	YZF R1 -99	H 917	21
	RN04	YZF R1 00-	e1*0063*	21
	RN09	YZF R1 02-	e13*0054*	35
	RP05	BT 1100 BullDog	e1*00116*	37
	4PU	XJR 1200	G 978	38
	RP02	XJR 1300	K 266	39
	RP06	XJR 1300	e1*00134*	40
	RP10	XJR 1300	e1*0204	40

Teilgutachten Nr.: 18 10 07 8302 (4. Neufassung)
 Hersteller: Fechter-Drive
 Typ: Tail Skirt TS

I. Verwendungsbereich

Fahrzeughersteller	Typ	Handelsbezeichnung	ABE-Nr. / EG-BE-Nr.	Ausführung	
Honda	JC 34	CBR 125 R	e*0004	50	
	PC 38	CBF 800	e*0231	51	
	PC34	CB 600 F	K 016	22	
	PC35	CBR 600 F 99-00	K 294	1	
	PC35	CBR 600 F 01-	e4*0101	2	
	PC35	CBR 600 FS 01-	e4*0101	2	
	PC36	CB 600F Hornet, CB 600S Hornet S	e3*0101	42	
	RC46	VFR 800 02-	K011	26	
	SC28	CBR 900 RR -97	G034	3	
	SC33	CBR 900 RR 96-	H294	4	
	SC42	X 11	e4*0026	27	
	SC44	CBR 900 RR 00-	e13*0019	5	
	SC36	VTR 1000 F	e13*0044	6	
	SC45	VTR 1000 SP 1	H 687	7	
	SC45	VTR 1000 SP 2 02-	H 687	28	
	SC48	CB 900 Hornet	e13*0051*	24	
	SC50	CBR 900 RR 02-	e13*0052	24	
	SC54	CB 1300	e4*0187*	24	
	Kawasaki	ZX600G	ZX-6R 96-	H 967	8
		ZX600J	ZX-6R 00-	e4*0042	8
ZX636-A1H		ZX 6R 02-	e4*0141	29	
ZX636B		ZX 6R	e4*0180	43	
ZR750J		Z 750	e1*0197*	44	
ZX900C		ZX-9R 98-	H884	9	
ZX900E		ZX-9R 00-	e4*00054	9	
ZX900F		ZX 9R 02-	e1*00054	30	
ZX1200C		ZZR 1200 02-		31	
ZXT20A		ZX 12R 02-	e1*00065	32	
ZRT00A		Z 1000	e1*0172*	44	

**CERTIFICATE
of Type Approval**

No: **0001-00059**

According to the

Test Report No. **EAF071694-00-1218**

ISOQA hereby certifies the samples with following details are complied with the related requirements :

Front & Rear Direction Indicator of ECE Regulation 50



Model No. **ST-171LED**

Signed by

Date of approval: **2006/1/10**

Arthur Chang

Arthur C. H. Chang

Chief Executive Officer
Integrated Service of Quality Assessment

This certificate is applicable to samples tested only.

This certificate is not a stand-alone document.

The certificate has to be used together with the

Certificate of Conformity of Production.

Expiry date: **2007/1/10**

E1/E11/DOT/SAE
Made in Taiwan
Approved by ISOQA
台灣生產，建維驗證

**CERTIFICATE
of Type Approval**

No: **0001-00159**

According to the

Test Report No. **EAH178908-001450**

ISOQA hereby certifies the samples with following details are complied with the related requirements :

Rear Position Lamp and Stop Lamp of ECE Regulation 50



Model No. **ST-5082LED**

R1 2007/2008

Signed by

Date of approval: **2007/7/02**

Arthur Chang

Arthur C. H. Chang

Expiry date: **2007/10/02**

Chief Executive Officer

Integrated Service of Quality Assessment

This certificate is applicable to samples tested only.

This certificate is not a stand-alone document.

The certificate has to be used together with the

Certificate of Conformity of Production.

E1/ E11/DOT/SAE
Made in Asia
Approved by ISOQA
亞洲製造. 建維驗證

THE NETHERLANDS
(N E D E R L A N D)

COMMUNICATION


Concerning:

- approval granted
- ~~- approval extended~~
- ~~- approval refused~~
- ~~- approval withdrawn~~
- ~~- production definitely discontinued~~

of a type of ~~front position lamps~~, rear position lamps, stop lamps, ~~direction indicators an rear-
registration plate illuminating devices~~ for mopeds, motor cycles and vehicles treated as such pursuant
to Regulation number 50.

Approval number: E4-50R-00 1332

Extension number: 00

1. Trade name or mark of the device :  (ST)
2. Manufacturer's name for the type of device : ST-3105CLED
3. Manufacturer's name and address : Yuan Jeou Industrial Company Limited
No.80, Yong An Road, Annan District, Tainan
City 709-69, Taiwan, Republic of China
4. If applicable, name and address of the manufacturer's representative : --
5. Submitted for approval on : 1 December 2008
6. Technical service responsible for conducting approval tests : KEMA Quality B.V.
7. Date of report issued by that service : 15 December 2008
8. Number of report issued by that service : 2121192-QUA/PHO 08-246-28
9. Concise description :





COMUNICACIÓN / COMMUNICATION:

Concerniente a (1):	LA CONCESION DE HOMOLOGACIÓN LA EXTENSIÓN DE HOMOLOGACIÓN LA DENEGACIÓN DE HOMOLOGACIÓN LA RETIRADA DE HOMOLOGACIÓN EL Cese DEFINITIVO DE PRODUCCIÓN
Concerning (1):	APPROVAL GRANTED APPROVAL EXTENDED APPROVAL REFUSED APPROVAL WITHDRAWN PRODUCTION DEFINITELY DISCONTINUED

de un tipo de luz de posición lateral marcada SM1/SM2 (1) en aplicación del Reglamento Nº91
of a type of side-marker lamp marked SM1/ SM2(1), pursuant to Regulation No91

Nº de homologación/ Approval No.: SM2-E9-00. 1268

Extensión Nº / Extension No.:-----

1. Marca de fábrica o de comercio de la luz de posición lateral/ Manufacturer's name for the type of side-marker lamp: LEADWIND
2. Designación del tipo de luz de posición lateral dado por el fabricante / Manufacturer's name for the type of side-marker lamp: LW-PG06SML
3. Nombre y dirección del fabricante / Manufacturer's name and address:
[Redacted]
4. Nombre y dirección del representante del fabricante (en su caso) / If applicable, name and address of manufacturer's representative: ---
5. Dispositivo sometido a homologación / Submitted for approval on: 30.09.2004
6. Servicio técnico encargado de los ensayos de homologación / Technical service responsible for conducting approval test: IDIADA
7. Fecha del acta de ensayos emitida por este servicio / Date of report issued by that service: 16.11.2004
8. Número del acta de ensayos emitido por dicho servicio / Number of report issued by that service: A0409025
9. Breve descripción / Concise description:
 - Color de la luz emitida: amarillo-auto/rojo (1) / Colour of the light emitted amber/red (1)
 - Número y categoría de la(s) lámpara(s) / Number and category of filament lamp(s): 4x LEDES
 - Módulo de fuente de luz: sí/no (1) / Light source module: yes/no (1)
 - Código de identificación específico del módulo de fuente de luz: / Light source module specific identification code: -----



(1) Táchese lo que no proceda / Strike out what does not apply

1 The Eastgate Office Centre
Eastgate Road
Bristol BS5 6XX
United Kingdom



Switchboard: +44 (0)117 951 5151
Main Fax: +44 (0)117 952 4103
E-mail: general@vca.gov.uk
Web Site: www.vca.gov.uk

VEHICLE CERTIFICATION AGENCY

THE UNITED KINGDOM VEHICLE APPROVAL AUTHORITY


Rev 10/02



COMMUNICATION CONCERNING THE APPROVAL GRANTED OF A TYPE
OF DEVICE PURSUANT TO REGULATION NO 50
(*Motorcycle Lamps and Illuminating Devices*)

Approval No: 50R-00 0358

1. Trade name or mark of the device:

Trade Mark: 
Trade Name: ST

2. Manufacturer's name for the type of device: ST-2049LED

3.

GSXR 1000 2003/2004

4. If applicable, name and address of the manufacturer's representative: Not applicable

5. Submitted for approval on: 15 November 2004

6. Technical service responsible for conducting approval tests: Vehicle Certification Agency

7. Date of report issued by that service: 19 November 2004

8. Number of report issued by that service: EAE061725





LE GOUVERNEMENT
DU GRAND-DUCHÉ DE LUXEMBOURG

Ministère des Transports

L-2938 Luxembourg

SOCIÉTÉ NATIONALE DE
CERTIFICATION ET D'HOMOLOGATION

s.à.r.l.

Registre de Commerce: B 27180

L-5201 Sandweiler



Référence: E13*10R00*10R02*3876*00

Annexes: - Rapport Technique
- Fiche de Renseignements du constructeur

Sandweiler, 26 septembre 2006

Communication concernant:⁽²⁾

Communication concerning:



- la délivrance d'une homologation

approval granted

- l'extension d'homologation

approval extended

- le refus d'homologation

approval refused

- le retrait d'homologation

approval withdrawn

- l'arrêt définitif de la production

production definitely discontinued

d'un type de sous-ensemble électrique/électronique⁽²⁾ en ce qui concerne le Règlement N° 10
of a type of electrical/electronic sub-assembly with regard to Regulation N° 10


Numéro d'homologation par type:

Approval number:

E13*10R00*10R02*3876*00

Marque d'homologation:

Approval mark:



1. Fabricant: (marque commerciale du constructeur):

Make (trade name of manufacturer):

SPRING LITE ELECTRONIC ENTERPRISE CO., LTD.

2. Type:

Type:

SPL-745

Dénomination(s) commerciale(s) générale(s):

General commercial description(s):

Super Bright Beam

Versión(s)/Variante(s):

Version(s)/Variant(s):

Refer to page 2 of manufacturer's information document

3. Moyens d'identification du type, s'ils sont marqués sur le véhicule / composant / entité technique⁽²⁾:

Means of identification of type, if marked on the vehicle / component / separate-technical-unit:

See item 6.

3.1. Emplacement de ce marquage:

Location of that marking:

See item 6.

Ermax[®]

**1074, Av. des carrières
Z.A. La plaine du caire III
13830 ROQUEFORT LA BÉDOULE
FRANCE**

**www.ermax.fr
accueil@ermax.fr
phone : +33 (0) 4 42 73 67 91/92
fax : +33 (0) 4 42 73 58 82**